

1/2

FIG. 1





FIG. 2



Best Available Copy

Technical drawing of a mechanical assembly. The drawing shows a perspective view of a component with several parts labeled with numbers and leader lines:

- 2**: Points to the main body of the component.
- 3**: Points to a rectangular block or housing.
- 8**: Points to a threaded section of a rod or shaft.
- 11**: Points to a dashed line indicating a hidden or internal feature.
- 12**: Points to a small, angled component at the bottom left.
- 14**: Points to a threaded section of a rod or shaft, appearing twice.
- 9**: Points to a cylindrical component on the right side.
- 10**: Points to a curved pipe or tube extending from the right side.